

367146



State of Ohio Environmental Protection Agency

**Southwest District Office**

401 E. Fifth St.  
Dayton, Ohio 45402

TELE: (937) 285-6357 FAX: (937) 285-6249  
[www.epa.state.oh.us](http://www.epa.state.oh.us)

Ted Strickland, Governor  
Lee Fisher, Lieutenant Governor  
Chris Korleski, Director

February 13, 2008

Ms. Karen Cibulskis  
US EPA  
SR-6J  
77 West Jackson St.  
60604, Chicago IL

**RE: South Dayton Dump photographs**

Hello Karen:

On February 7<sup>th</sup> Ohio EPA did a walk-over of the site. Of particular notice, we observed clusters of rusted drums in two distinct areas. The first area was an east to west trending depression south of Valley Asphalt, Figure 1. The second area was a depression south of the former air curtain destructor. These features correspond to the extent of a former haul road, as observed in the attached 1973 aerial photograph, Figure 2. The enclosed CD contains photographs of these and other features.

Sincerely,


A handwritten signature in cursive script that reads "Matt Justice".

Matt Justice  
Site Coordinator  
Division of Emergency and Remedial Response

Enclosure

S. Dayton Dump  
Ohio EPA Observed Drum Locations, Feb. 7, 2008

Figure 1



1 inch = 150 feet  
Scale 1: 1,800  
Mont. Co. 2007 aerial photograph


Monitoring Wells  
EPA, Observed Drum Area, 2/7/08  
Site Boundary, 9/29/05





S. Dayton Dump  
Observed Drums Feb. 7, 2008 compared to April 1973

Figure 2



0 75 150 300 Feet

1 inch = 150 feet  
Scale 1: 1,800

Ohio DOT aerial photograph



Monitoring Wells



OEPA, Observed Drum Area, 2/7/08

Site Boundary, 9/29/05

N

OhioEPA